

# HIGHLIGHTS IN JULY 2018

---

During the month of July there were big trucks around hauling sand and topsoil. The bricklayers were here prepping surfaces and doing all the brickwork—nearing the completion of the outside of the building.



Pallets of bricks waiting their turn!



Bricks getting to their destination!







Chapel prep work



Working on the chimney on south side of the building near the entrance.



Brickwork on Chapel done





West side of the North Wing




Chimney work continues.



Work being on the front pillars



Brickwork done on front pillars



The Chimney is done